



So You Spilled a Pyrophoric Chemical, What Should You Do?

Appropriate Extinguishing Agents:

- Dry Sand
- Met-L-X
- Soda Ash (Na_2CO_3)
- Lime (CaO)

Pyrophoric Spill



In a Fume Hood

On a Person or in Transport

Large Spill

Small Spill

Safety Shower IMMEDIATELY

Close Sash, Evacuate Lab, Pull Fire Alarm

Remove Lab Coat and ALL Clothing

Extinguish with Appropriate Agent (see top left)

Quench: Per Lab Protocol if Controllable

Remain in Safety Shower for at Least 15 Minutes



Ensure ALL Essential Emergency Contacts are Notified

Once Extinguished Ensure Affected Person is Escorted to a Health Center or Hospital



EMERGENCY CONTACT INFORMATION

911
 PI: _____
 Office: _____ Cell: _____
 EH&S: (530) 752-1493
 Fire Department (campus): (530) 752-1236
 Safety Coordinator: _____
 Other: _____